

## Work Permit # <u>DRL-2011-006/SS-2011-</u> Work Order # \_\_\_\_\_ Job# \_\_\_\_ Activity# \_\_\_\_

Work requester fills out this section.	☐ Standing W	☐ Standing Work Permit					
Requester: Don Lynch	Date: 4/12/2011	Ext.: 2253	Dept/Div/Group: PO/PHE	ENIX			
Other Contact person (if different from	requester): Jim LaBounty		Ext.: 3774				
Work Control Coordinator: Don Lynch		Start Date: 4/13/2011	Est. End Date: 4/30/2011				
	00 lb Aerogel on Northwest end of Wes						
Building: 1008	Room: IR	Equipment: 1 ton crane	Service Provider: PHENI	IX			
CC, Requester/Designee, Service Provi	ider, and ES&H (as necessary) fill out	this section or attach analy	ysis				
ES&H ANALYSIS	Ast at a		On the selection	□D. F.C.			
	None ☐ Activation Radiography ☐ M	Airborne loisture Density Gauges	Contamination	Radiation X-ray Equipment			
	d, notify Isotope Special Materials Group	, ,					
Safety Concerns	None	Ergonomics	☐ Fissionable materials involved, notify Laboratory Criticality Officer ☐ Transport of Haz/Rad Material				
,	Confined Space*	Explosives	Lead*	Penetrating Fire Walls			
☐ Adding/Removing Walls or Roofs	Corrosive	☐ Expresives ☐ Flammable	☐ Magnetic Field*	☐ Pressurized Systems			
☐ Asbestos*	☐ Cryogenic	☐ Fumes/Mist/Dust*	Material Handling	Rigging/Critical Lift			
☐ Beryllium*	☐ Electrical	☐ Heat/Cold Stress	☐ Noise*	☐ Toxic Materials*			
☐ Biohazard*	☐ Elevated Work*	☐ Hydraulic	☐ Non-ionizing Radiation*	☐ Vacuum			
☐ Chemicals*	☐ Excavation	☐ Lasers*	Oxygen Deficiency*	☐ Other			
* Does this work require medical clear	rance or surveillance from the Occupation	onal Medicine Clinic?   Ye	s 🔀 No	•			
Environmental Concerns		None     Non	☐ Work impacts Environmenta	al Permit No.			
☐ Atmospheric Discharges (rad/nor	n-rad)	☐ Land Use	Soil	☐ Waste-Mixed			
☐ Chemical or Rad Material Storage	<u> </u>	☐ Liquid Discharges	Activation/contamination  Waste-Clean	☐ Waste-Radioactive			
	e or ose	Oil/PCB	<del>                                     </del>				
Cesspools (UIC)		Management	☐ Waste-Hazardous	☐ Waste-Regulated Medical			
☐ High water/power consumption		☐ Spill potential	☐ Waste-Industrial	☐ Underground Duct/Piping			
Waste disposition by:				☐ Other			
Pollution Prevention (P2)/Waste Mi	nimization Opportunity:	None ☐ Yes					
FACILITY CONCERNS	None     Non						
☐ Access/Egress Limitations	Electrical Noise	☐ Potential to Cause a F		Vibrations			
_ ,	☐ Impacts Facility Use Agree		☐ Temperature Change	Other			
Configuration Control	Maintenance Work on Vent	tilation Systems	Utility Interruptions				
WORK CONTROLS Work Practices							
None	Exhaust Ventilation	Lockout/Tagout	Spill Containment	Security (see Instruction Sheet)			
		☐ Posting/Warning	<del>                                     </del>				
Back-up Person/Watch     Back-up Pers	☐ HP Coverage	Signs	☐ Time Limitation	Time Limitation			
☐ Barricades	☐ IH Survey	☐ Scaffolding-requires	☐ Warning Alarm (i.e. "high level")				
		inspection		,			
Protective Equipment  None	☐ For Dlugg	Gloves	☐ Lab Coat	Safety Glasses			
Coveralls	☐ Ear Plugs ☐ Ear Muffs	<del>                                     </del>	<del>-</del>	Safety Harness			
				▼ Safety			
☐ Disposable Clothing	☐ Face Shield		☐ Shoe Covers	Shoes Other			
Permits Required (Permits must be							
None     Non	☐ Cutting/Welding	☐ Impair Fire Protection	•				
Concrete/Masonry Penetration	☐ Digging/Core Drilling	Rad Work Permit-RW	'ermit-RWP No				
Confined Space Entry	☐ Electrical Working Hot	Other					
Dosimetry/Monitoring		I					
None	☐ Heat Stress Monitor	Real Time Monitor	☐ TLD				
☐ Air Effluent	☐ Noise Survey/Dosimeter	Self-reading Pencil Dosimeter	☐ Waste Characterization				
Ground Water	O <sub>2</sub> /Combustible Gas	Self-reading Digital Dosimeter	☐ Other				
☐ Liquid Effluent	☐ Passive Vapor Monitor	Sorbent Tube/Filter Pump					
Training Requirements (List below s							
PHENIX Awareness, C-A Access, Cra	ane operator						
Based on analysis above, the Walk ratings below:	down Team determines the risk, com	plexity, and coordination	If using the permit when all hazard ratings are low, only the following need to sign: ( Although allowed, there is no need to use back of form)				
ES&H Risk Level:		High	WCC:	Date:			
Complexity Level:		 ☐ High	Service Provider:	Date:			
Work Coordination:	☐ Low ☑ Moderate	☐ High	Authorization to start Date:				
		<del>-</del>	(Departmental Sup/MCC/Design	(Departmental Sup/WCC/Designee)			

Work Plan (procedures, timi This work is skill of the craft. I lift procedure is attached.	ng, equipment, and personnel availability nee involves use of crane while flammable gas is	ed to be addressed) in use in the PHEN	): IIX detector. Crane	operator and wat	ch person shall h	nave current crane operator training. The	
Special Working Conditions F None	Required:						
Operational Limits Imposed:	None						
Post Work Testing Required:							
Job Safety Analysis Required			Walkdown Requ				
Tob carety ranaryole recognition			Trainaomiritoqu	ou. <u>/                                   </u>			
Reviewed by: Primary Review that the hazards and risks that	ewer will determine the size of the review tear at could impact ES&H have been identified ar	m and the other sig	natures required baccording to BNL	ased on hazards a requirements.	and job complexit	ty. Primary Reviewer signature means	
<u>Title</u>	Name (print)	Signature		Life #		<u>Date</u>	
Primary Reviewer							
ES&H Professional							
Other							
Other							
Work Control Coordinator	Don Lynch			20146		2/27/2006	
Service Provider	Don Lynch			20140		2/21/2000	
Service Flovider	Davidani Davas III in carden	☐ team					
	Review Done: in series	L team					
Job site personnel fill out this se	ection.						
Note: Signature indicates per	rsonnel performing work have read and unde	erstand the hazards	and permit require	ments (including a	any attachments)		
Job Supervisor:	Job Supervisor:		Contractor Supervisor:				
Workers:	Life#:	Life#:		Workers : Life#:			
Workers are encouraged to p	rovide feedback on ES&H concerns or on ide	eas for improved job	work flow. Use fe	edback form or sp	ace below.		
<u> </u>				·			
	/ork Control Coordinator/Designee						
Conditions are appropriate to	Conditions are appropriate to start work: (Permit has been reviewed, work				T _	D.	
Name:	Signature:		Life#:		Date:	Date:	
Departmental Job Supervisor, W	/ork Requester/Designee determines if Po	st Job Review is r	equired. 🗌 Yes	☐ No			
Post Job Review (Fill in name	es of reviewers)						
Name: Signature:			Life#:		Date:	Date:	
Name: Signature:			Life#:		Date:	Date:	
	<u>l</u>						
Worker provides feedback.  Worker Feedback (use attach a) WCM/WCC: Is any feedback.	ned sheets as necessary) ack required?						
b) Workers: Are there better	methods or safer ways to perform this job in	the future? \( \subseteq \text{ Ye}	es 🗌 No				
Closeout: Work Control Coordin	nator (authorizing dept.) checks quality of ervisor)	completed permit	and ensures the	work site is left ir	n an acceptable	condition. (WCC can delegate	
Name:	Signature:		Life#:		Date:		
Comments:	1						

## Crane operating procedure: Lifting Aerogel Mainframe to Aerogel west rack (north end of west side of West Carriage):

- 1. Manually bring load into IR to be lifted as close as possible to final destination.
- 2. Notify PHENIX shift leader of intention to use crane
- 3. Get crane lockout key from lockbox
- 4. Make sure all magnets are off before unlocking crane and magnet keys are locked and tagged.
- 5. Inspect crane to verify it is proper working condition and its inspection records are up to date. Unlock crane.
- 6. Retract hooks (if necessary) to their highest position before moving crane.
- 7. Position crane 1<sup>st</sup> hook directly over object to be lifted. (Note: crane path to load must be outside of the Central detector area, i.e. must move north and south while west of the west carriage or east of the East carriage, and must move north and south while South of the south muon magnet or north of the north muon magnet.)
- 8. Rig the replacement mainframe and lift the load to the lower "window washer" platform and position load near the west side of the Aerogel rack, minimizing any sway or otherwise excessive motion.
- 9. Place new mainframe on the platform deck near the Aerogel rack.
- 10. After load has been placed remove hook and rigging and retract to uppermost position.
- 11. Manually remove failed mainframe and place on the window washer platform.
- 12. Manually install the replacement Aerogel mainframe.
- 13. Rig the failed mainframe, lift and move failed mainframe. To same location as replacement mainframe was lifted from, following a path outside of the Central detector area as described above.
- 14. Move crane to stow location.
- 15. Manually remove the failed mainframe from the IR to the PHENIX electronics testing area for evaluation and disposition.
- 16. Lockout crane and return key to lockbox
- 17. Inform shift leader that crane use is completed

As flammable gas is normally circulating in the IR during operation, any use of the crane which brings or could bring any part of the crane, rigging, or item being lifted within 5 feet of any component of the DC, PC, TEC, and/or MuID detectors requires extra care to assure that there is no potential for a spark or other ignition source from any part of the crane, rigging, or item being lifted.